


# SMT POWER INDUCTORS



## SMT POWER INDUCTORS (SDO/SDOS TYPE)

### CONFIGURATIONS


#### SDO-1608




Marking





#### Land Pattern




#### SDOS-1608




Marking





#### Land Pattern




#### SDO-3316




Marking





#### Land Pattern




#### SDOS-3316




Marking





#### Land Pattern




#### SDO-5022




Marking





#### Land Pattern



#### SDOS-5022



Marking



#### Land Pattern

